

**10 Most Commonly Cited LSC Deficiencies  
National with Regional Comparison**

	K18	K29	K62	K147	K38	K56	K25	K50	K144	K67
<b>National</b>	38%	31%	27%	27%	23%	21%	21%	20%	19%	16%
<b>Region VII</b>	43%	38%	41%	41%	24%	31%	28%	21%	25%	7%
<b>Iowa</b>	40%	35%	24%	45%	20%	46%	29%	15%	45%	11%
<b>Kansas</b>	73%	66%	71%	69%	36%	20%	49%	37%	24%	13%
<b>Missouri</b>	34%	23%	45%	18%	23%	26%	19%	16%	12%	1%
<b>Nebraska</b>	10%	26%	14%	43%	12%	34%	8%	18%	10%	1%

**National 2007 Citation Frequency**

K18	37.60%	CORRIDOR DOORS
K29	31.30%	HAZARDOUS AREAS - SEPARATION
K62	27.40%	SPRINKLER SYSTEM MAINTENANCE
K147	26.50%	ELECTRICAL WIRING AND EQUIPMENT
K38	22.70%	EXIT ACCESS
K56	21.10%	AUTOMATIC SPRINKLER SYSTEM
K25	20.70%	SMOKE PARTITION CONSTRUCTION
K50	20.00%	FIRE DRILLS
K144	18.50%	GENERATORS INSPECTED/TESTED
K67	16.10%	VENTILATING EQUIPMENT
K69	14.80%	COOKING EQUIPMENT
K76	14.20%	MEDICAL GAS SYSTEM
K12	13.70%	CONSTRUCTION TYPE
K52	13.10%	TESTING OF FIRE ALARM
K27	12.30%	DOORS IN SMOKE PARTITIONS

**Region VII 2007 Citation Frequency**

K46	43.70%	EMERGENCY LIGHTING
K18	43.10%	CORRIDOR DOORS
K62	41.40%	SPRINKLER SYSTEM MAINTENANCE
K147	40.80%	ELECTRICAL WIRING AND EQUIPMENT
K29	37.50%	HAZARDOUS AREAS - SEPARATION
K56	31.30%	AUTOMATIC SPRINKLER SYSTEM
K12	28.20%	CONSTRUCTION TYPE
K25	28.00%	SMOKE PARTITION CONSTRUCTION
K45	25.30%	EXIT LIGHTING
K144	25.00%	GENERATORS INSPECTED/TESTED
K38	23.90%	EXIT ACCESS
K69	22.30%	COOKING EQUIPMENT
K50	20.90%	FIRE DRILLS
K66	18.60%	SMOKING REGULATIONS
K51	17.00%	FIRE ALARM SYSTEM

### Iowa 2007 Citation Frequency

K46	49.90%	EMERGENCY LIGHTING
K56	45.60%	AUTOMATIC SPRINKLER SYSTEM
K144	44.80%	GENERATORS INSPECTED/TESTED
K147	44.50%	ELECTRICAL WIRING AND EQUIPMENT
K18	40.20%	CORRIDOR DOORS
K29	35.40%	HAZARDOUS AREAS - SEPARATION
K12	33.50%	CONSTRUCTION TYPE
K45	30.80%	EXIT LIGHTING
K25	29.00%	SMOKE PARTITION CONSTRUCTION
K62	23.60%	SPRINKLER SYSTEM MAINTENANCE
K69	22.30%	COOKING EQUIPMENT
K38	19.60%	EXIT ACCESS
K52	19.00%	TESTING OF FIRE ALARM
K47	18.20%	EXIT SIGNS
K51	18.20%	FIRE ALARM SYSTEM

### Kansas 2007 Citation Frequency

K18	73.10%	CORRIDOR DOORS
K62	71.00%	SPRINKLER SYSTEM MAINTENANCE
K147	68.50%	ELECTRICAL WIRING AND EQUIPMENT
K29	66.40%	HAZARDOUS AREAS - SEPARATION
K46	62.90%	EMERGENCY LIGHTING
K25	48.60%	SMOKE PARTITION CONSTRUCTION
K74	42.70%	COMBUSTIBLE CURTAINS
K12	41.30%	CONSTRUCTION TYPE
K50	36.70%	FIRE DRILLS
K38	36.40%	EXIT ACCESS
K45	36.00%	EXIT LIGHTING
K66	32.90%	SMOKING REGULATIONS
K69	30.40%	COOKING EQUIPMENT
K76	29.40%	MEDICAL GAS SYSTEM
K134	28.70%	EMERGENCY SHOWER


### Missouri 2007 Citation Frequency

K62	44.70%	SPRINKLER SYSTEM MAINTENANCE
K18	34.40%	CORRIDOR DOORS
K46	29.60%	EMERGENCY LIGHTING
K56	25.50%	AUTOMATIC SPRINKLER SYSTEM
K66	23.10%	SMOKING REGULATIONS
K38	22.60%	EXIT ACCESS
K29	22.60%	HAZARDOUS AREAS - SEPARATION
K54	22.60%	SMOKE DETECTOR MAINTENANCE
K12	18.80%	CONSTRUCTION TYPE
K25	18.80%	SMOKE PARTITION CONSTRUCTION
K147	18.00%	ELECTRICAL WIRING AND EQUIPMENT
K50	16.30%	FIRE DRILLS
K69	15.90%	COOKING EQUIPMENT
K45	15.90%	EXIT LIGHTING
K144	12.30%	GENERATORS INSPECTED/TESTED


### Nebraska 2007 Citation Frequency

K147	42.40%	ELECTRICAL WIRING AND EQUIPMENT
K56	33.90%	AUTOMATIC SPRINKLER SYSTEM
K46	27.10%	EMERGENCY LIGHTING
K29	26.30%	HAZARDOUS AREAS - SEPARATION
K69	25.40%	COOKING EQUIPMENT
K50	17.80%	FIRE DRILLS
K45	15.30%	EXIT LIGHTING
K62	14.40%	SPRINKLER SYSTEM MAINTENANCE
K52	14.40%	TESTING OF FIRE ALARM
K76	13.60%	MEDICAL GAS SYSTEM
K12	12.70%	CONSTRUCTION TYPE
K38	11.90%	EXIT ACCESS
K51	11.90%	FIRE ALARM SYSTEM
K18	10.20%	CORRIDOR DOORS
K72	10.20%	FURNISHING AND DECORATIONS

# Life Safety Code Deficiency Averages 2005-2007



# ISC Citation Frequency



# Hospital Based Nursing Home LSC Deficiency Averages 2003-2007

